



### POWERHOUSE B LUBE OIL

Indar started already the oil filling to generator bearing at lube oil assembly unit 1 and likewise flushing of lube oil pipes line at unit 2.



### POWERHOUSE B TRANSFORMER

Asiaphil conducted a test on power transformer last February 5, 2010 at powerhouse B substation. Likewise, the grounding connections of metallic structure at voltage transformer was being done in preparation for the scheduled energization of the transmission line.

INSIDE THIS ISSUE:	
Powerhouse B Lube Oil	1
Powerhouse B Transformer	1
Powerhouse B SCADA	2
Headpond A	2
Desander B	2
Penstock A	3





### POWERHOUSE B SCADA

Set up of SCADA and PLC at powerhouse B control room is still on going and being done by Indra. At the same time, the labeling of control cables at turbine governor and Automatic Voltage Regulator (AVR) at unit 2 and control cables termination for the generators are still on going.



### HEADPOND A

Compaction and rockfilling activities for headpond A is still on going.



### DESANBER B

Concrete pouring of wall, top slab and flushing outlet (right side) and installation of railings for desader B is still on going.

**PENSTOCK A**

Manual excavation of AB25 while rock bolting at AB24 is still on going. At the same time, WITCO conducted radiographic examination of the remaining penstock joints to ensure the good quality of the pipelines.

**CHARGING OF NITROGEN AT HPU UNIT****HEADPOND A SPILLWAY**